

# SKIRTING MANTAINANCE

Technacal brochure



## Storage

The ideal environmental conditions for a warehouse are a 20° C (68° F) temperature and a relative humidity environment between 50 and 70 %.

Store skirtings in horitzontal position on a completely flat surface to avoid deformations. Avoid direct sunlight and high humidity.

## Installation

Place the material for a minimum of 48 hours in the same location and with the same climatic conditions where it will be installed.

The floor and the wall must be perfectly leveled, completely dry, clean and firm.

Do not stack more than six boxes of material.

Open boxes completely before removing the material, never stretch the material by the heads of the box.

## Cleaning

Use a damp cloth to clean the skirting, with care not to leave the skirting or the floor wet. Do not use abrasives liquids or solvents liquids or cleaners with ammonia, these can damage the skirting.

## Life Evolution

On wooden skirtings keep in mind that wood is a living material and as such can evolve slightly on contact with sunlight. Little changes are proof that this is a truly natural product. For both wood and laminate foil avoid sudden changes in light, because UV light could cause pitch changes .

## PERFILSTAR S.A.

Av. Torre Mateu num. 77, naves 4,5,6 - P.I. Can Salvatella

Barberà del Vallès - 08210 - Barcelona - Spain

Phone: 00 34 93 729 11 39 - Fax: 00 34 93 719 20 44

perfilstar@perfilstar.com

[www.perfilstar.com](http://www.perfilstar.com)